

Site Construction Update - Week of 23-Nov-2020 to 28-Nov-2020

1. Shoring works pile drilling on-going along Southwest radius of site
2. Loading & exporting of shoring drilling spoils
3. Daily concrete supply deliveries for piles
4. Steel pile deliveries & on-going splicing of piles on site
5. Dewatering of site active (settlement tank & discharge point located at North side of Galleria Mall)
6. On-going bulk excavation & associated daily hauling
7. Tieback installation works along North & East perimeter shoring walls