

Site Construction Update - Week of 16-Feb-2021 to 20-Feb-2021

1. Dewatering wells active throughout site (settlement tank & discharge point located at North side of Galleria Mall)
2. On-going bulk excavation to depth of second & third row tiebacks, shaving of caisson walls, & associated daily exporting
3. Second row production tieback installation works & stressing
4. Shoring wall frost protection installation works